

## No License Found Error on MaveriX/ESi2 Cal

Ocasionally when doing an ESi2 calibration on the MaveriX, an error message may pop up that says "No License Found". If you have just updated the software to 1.6.4, go into System then go to "Activations" under "Feature Licenses" on the left hand menu. Ensure that the EDM1 and AC110 are there and have a green dot. If they do, reboot the MaveriX. This should clear the issue and you can continue with the calibration. This may occur with MaveriX monitors that have been updated previous to you receiving them. Follow the same instructions. If there are any issues after following these instructions, please, call 1-800-247-3808 option 1 or email [support@outbackguidance.com](mailto:support@outbackguidance.com).

