



Speed Sync Inversion



User must correct vehicle direction of travel.

Examples of Speed Sign Inversion causing map flips.



Speed sign synchronizer was added to better manage a speed sign error.

If the synchronizer is not checked user must ensure manually correct direction of vehicle travel on initial movement.

If synchronizer is checked the heading is corrected thru curvature and corrects direction automatically.

There have been user experiences whereas sudden starts / stops or K Turns can trigger unwanted map flips. Next release resolves these edge case issues.