

CANBUS Steer-Ready Cal Error

When you go to calibrate the CANBUS (Hyd Danfoss, Hyd Danfoss CLS, and AGCO Track) there is an error on the screen. A configure button will appear under all the CANBUS SR valve types. The configure button is to be used ONLY for the Hyd. Danfoss. The AGCO Track and Hyd. Danfoss CLS do NOT use it. The AGCO and Hyd. Danfoss CLS only need the roll and pitch bias calibration completed. This should be corrected on the next software release.

