

Date: 06-08-2022

Equipment	Model	Rate Controller	Part Number	Notes:
Apache	710, 1010 1210	SCS 4400	911-0001-000	
	AS710, AS1010, AS1210 AS720, AS1020, AS1220	SCS 460 & 5000	911-0011-000	STX and S3 not compatible
Ag-Chem	Rogator 854	SCS 661	911-0019-000	Adapter Kit for PWM valves ONLY *must be ordered with 911-0002-000
	Rogator 1254	SCS 460	911-0006-000	STX and S3 not compatible
	Rogator 1254, 1264, 1274 (05' and older)	SCS 661	911-0019-000	Adapter Kit for PWM valves ONLY *must be ordered with 911-0002-000 or 911-0006-000 (External Switches)
Spra-Coupe	3000/4000 series	SCS 460	911-0004-000	STX and S3 not compatible
	7450, 7460 7650, 7655, 7660	Raven CAN Node Harness Required	911-0017-000	STX and S3 not compatible Supports series with factory installed pump switch, contact Outback Customer Service if you are unsure
Case IH SPX	3150, 3185, 3200, 3200-B	SCS 460	911-0009-000	STX and S3 not compatible
Willmar	8100/8500	Mid-Tech	911-0007-000	STX and S3 not compatible
Flexi-Coil		SP-655	911-0013-000	
Miller Nitro	5000		911-0012-000	STX and S3 not compatible Excludes external switches Harness only supports 5 sections. Contact Outback Customer Service if equipped with 10 sections
General	Excludes any Models with External Switches	TeeJet 844E/854	911-0003-000	Excludes some controllers where switches are not part of the main console. Contact Outback Customer Service for additional detail.
		Raven 440/450	911-0002-000	Positive Close feature is not supported in S3 Excludes machines with wireless boom control box.
		Raven 460/660/661		Contact Customer Service for additional details. See 911-0019-000 for machines with Raven 661 & PWM valves
		Raven 4400	911-0001-000	Positive Close feature is not supported in S3 Excludes machines with wireless boom control box.
		Raven 4600		Contact Customer Service for additional details.
Ag Leader	Planters	SureStop Clutches	911-0014-000	STX and S3 not compatible
Tru-Count	Planters	Air - 8 Section	911-0008-000	STX and S3 not compatible
Single Product Dry	Single Product Dry Spinner Spreaders only	Not Required	911-0010-000	Maverix, STX and S3 not compatible Specific Machine Control components required Additional adapter/extension cables may be required