

Retrieving CAN Data Logs

Navigate to diagnostics>files>CAN.


Insert USB and ensure device is recognized.

Select the corresponding CAN0 log to be transferred.

Press the transfer to icon.



Ensure the CAN0 log selected is transferred to USB.



CAN1 logs are only required when AC110 connected.

Select the corresponding CAN1 log to be transferred.

Press the transfer to icon.

Ensure all CAN logs required are transferred to USB.

